Question 23 (3 marks)

Describe the process you should use to measure a resistor with a nominal value of 1KΩ, using an analogue ohmmeter.   **3**

To measure the nominal 1KΩ resistor. First make sure the needle is zeroed out at exactly zero. Next connect the ohmeter to the resistor with the right polarities at each end. When the needle moves take the reading being careful to read the right scale on the meter.