


Question 6

What correct safety procedure should you follow if an electric power tool has a frayed lead?

- A Report it to your supervisor and attach a fault tag.
- B Immediately tape up the damaged lead with insulation tape.
- C Report it to your supervisor, but if it is a double-insulated tool it is safe to use.
- D Continue to use it, provided it is connected to an earth leakage breaker (ELB).

HSC Statistics on this Question:



	Band 1/2	Band 2/3	Band 3/4	Band 4/5	Band 5/6
A	67%	95%	95%	100%	100%
B	33%	5%	3%	0%	0%
C	0%	0%	2%	0%	0%
D	0%	0%	0%	0%	0%
N	0%	0%	0%	0%	0%

The table and graph show, for the groups of students whose marks in the examination corresponded to the borderline between two bands, what percentages of each group selected the responses A, B, C and D. N is used to identify: No valid response.

Note that apparent anomalies in the table and graph, such as 0% or 100% of students choosing a particular response, can occur when there are no students (or very few students) who scored the particular examination mark associated with that borderline.