

	Josure the customer that you will do all that you can to have
	the the problem fixed as soon so possible.
1	For determine what is coursing the loss of suffly first find the main
	switch board: thech to see if the circuit breader for that sections
	sub switch board has been beiffed on turned off by mistake.
2	try to him it on once you have warned persons to wante the
	arece. If it luns on and does not trip off after a length of time
	that may well have been the problem.
3)	Aled the sub switch board for any problems like the main
	switch being tripped. If you find a tripped witch for the board
	hun it on. It it trips again there may be a more serious problem
	isolate fower to the board and place a danger of tag or lock
	out the sixth. Lest earth continuity on the circuits in the
	over to see if there is a major earth lealuge in one of the
	circuits feldel

