

Start here.

22a)

~~Risk~~

Tools & Procedures	Risk	Solution
hand tools <sup>hammers, files</sup> ( <del>hammers, files</del> )	- cutting yourself	- Be careful and use proper techniques.
drilling	- hearing damage - injured by offcuts.	- Wear ear protection - Wear safety goggles, long pants & long sleeve shirt.
powered tools	- Electrocution	- make sure equipment is tagged and don't touch <sup>exposed</sup> loose wire.

- make sure all equipment is tagged & up to date.

~~General Safety~~

General Safety

- Make sure all machinery have guards and safe zones marked around them.

risk - guillotine injuring worker  
solution - protective guards.

Risk - ~~any~~ chemical exposure from tools or machines

Solution - have washing stations nearby & materials safety data sheets so ~~employees~~ workers can know what they are dealing with.

General Safety

- make sure worker is properly trained on equipment and OHS guidelines

- Hair tied back, no loose clothing.

- PPE must be worn (glasses, Apron)